

# LNERCA Fleet Status as at November 1, 2024

<u>Coach No.</u>	<u>Location</u>	<u>Current status</u>
Gresley BTO 43567	NYMR	Undergoing repairs. Requires new tyres.
Gresley TTO 56856	NYMR	Available for traffic.
Thompson TK E1623E	NYMR	Requires new tyres.
Gresley RB 641	NYMR	Awaiting attention to springs.
Gresley TTO 23956	NYMR	Awaiting attention to axleboxes.
<b>Vehicles for possible use in Service Set</b>		
Gresley TK 23896	Kirby Misperton	Awaiting resumption of work.
Thompson CL 88339	Kirby Misperton	At Rampart, Barrow Hill, work in progress.
Gresley TTO 24109	NYMR	Stored at Levisham - partially restored.
Thompson CK E18477E	NYMR	Stored at Levisham - partially restored.
Gresley BTK 3669	Kirkby Stephen	Available for traffic.
Gresley TTO 43632	Akins shed	LNERCA undertaking remedial work.
<b>Special Use LNERCA Vehicles</b>		
ECJS RTO 189	Atkins shed	Being restored in Atkins shed, Pickering.
NER TO 945	NYMR	Stored in Carriage Stable awaiting attention.
<b>Vehicles for storing materials</b>		
Thompson BG E110E	Levisham	Stored under canvas.
Gresley RF 42969	Pickering Yard	In Beck Siding used as upholstery store.
Fish Van E75169E	Pickering Yard	Waiting roof sheet and door fitting.
CCT E1308E	Pickering Yard	In Beck Siding used as stores vehicle.
<b>Other carriages</b>		
ECJS TK 377	Embsay	Stored under cover.
Thompson Buffet E1706E	Embsay	Available for traffic
Gresley TK 3857	K. Stephen	Stored under canvas.
Gresley SLT 1299	Grosmont	Stored under canvas.
Gresley BCK 10178	Grosmont	Stored under canvas.
Gresley TK 3291	Grosmont	Stored under canvas.
NER RFO 2118	Kirby Misperton	Stored in shed awaiting restoration plan.
NER LC 1111	Kirkby Stephen	Stored. Stainmore Railway Company undertaking renovation.
GN Saloon 3087	Kirby Misperton	Varnishing underway at Kirby Misperton.
Gresley TTO 43654	Kirby Misperton	At paddock site, overhaul being planned.
Gresley TK 23890	Kirby Misperton	Stored under canvas.